

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2017

Submitted Date:

08/04/2017

Document Number:

679100103**FIELD INSPECTION FORM**

Loc ID 312997	Inspector Name: KUBECZKO, DAVE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:

OGCC Operator Number: 10525

Name of Operator: SANTA FE NATURAL RESOURCES INC

Address: 4833 FRONT STREET UNIT B 506

City: CASTLE ROCK State: CO Zip: 80104

Contact Information:

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Michael Sullivan MICHAEL		durangopl@earthlink.net	

General Comment:

Date of Inspection: 06-07-17

Type of Inspection: Containment, Stormwater, Fracing

Location Name: McIntyre 1-3R Pad; McIntyre 1-3ST Well;

Location ID #: 312997

API #: 05-081-06608

Observed site stormwater/erosion control and attempted frac on 06-07-17; site is partially reclaimed with natural vegetation; some weeds present; minor evidence of soil staining around wellhead; tank has secondary containment and adequate signage; stormwater/erosion controls are adequate - no indication of offsite migration of fluids or sediment from well pad; operator attempted to complete two stages of the frac, however during pressure up after setting packer, pressures dropped almost immediately; operator indicated there were issues with the production casing and would need to abort the frac and abandon the lateral; operator indicated that they would sundry a report of the work attempted and done.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401365909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217479