



looking east along WCR 20.5
two earthen dams constructed in drainage ditch to south of county road are
cause of ponding of surface water
Installation/construction of buried electric lines by local utility (United Power?)

8.8.2017 09:31