

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2017

Submitted Date:

08/07/2017

Document Number:

677900288

FIELD INSPECTION FORM

Loc ID 312854 Inspector Name: FISCHER, ALEX On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 36200
 Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO
 Address: 3600 S. YOSEMITE ST - STE 900
 City: DENVER State: CO Zip: 80237-

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	
		sharonsotoole@gmail.com	
Arthur, Denise		denise.arthur@state.co.us	
		ecooper@sierra-hamilton.com	
Colby, Lou		lou.colby@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Edelen, Randy		r.edelen@grynberg.com	
Griggs, Mary		mgriggs@sierra-hamilton.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100600	PIT	CL			-	CHIVINGTON 1	EI
100601	PIT	CL			-	CHIVINGTON 1	EI
222617	WELL	SI	05/07/2013	OW	081-05709	CHIVINGTON 1	EI

General Comment:

On August 3, 2017 COGCC Environmental Staff (Alex Fischer), conducted an inspection of Grynberg Petroleum Company, (Grynberg) Location ID 312854, Pit Facility ID 100600, Remediation (REM) 8333. Jerry Hoberg (Moffat County Planning) was present. Weather was partially cloudy and temperatures about 70 degrees Fahrenheit at time of Inspection. REM 8333 had been an ongoing remediation since about April 2014 and was closed in June of 2017.

NOTE; CONTACT

Colby, Lou - Area (142) Reclamation Inspector
 lou.colby@state.co.us
 (970) 876-1969
 (970) 989-4402 (cell)

Arthur, Denise - Reclamation Supervisor
 denise.arthur@state.co.us
 (303) 894-2100 x5195
 (720) 630-6533 (cell)

Inspected Facilities

Facility ID: 100600 Type: PIT API Number: - Status: CL Insp. Status: EI

Facility ID: 100601 Type: PIT API Number: - Status: CL Insp. Status: EI

Facility ID: 222617 Type: WELL API Number: 081-05709 Status: SI Insp. Status: EI

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail	Other	Fail			
<p>Comment:</p> <ul style="list-style-type: none"> There appeared to have been a recent precipitation event, as debris flow (vegetation) was noted about 6-8 inches entangled in the fence coming on Location from the west and off of Location to the east. Sediment had moved across and off of Location. Erosion features were noted across Location. <p>RANDY EDLIN AND MARY GRIGGS WERE CONTACTED ON 8/7/207 REGARDING SEDIMENT DISCHARGE OFF OF LOCATION.</p>						Date: <u>08/09/2017</u>
<p>Corrective Action: 1002.f, Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.</p>						
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments		
Comment	User	Date
<p>On August 3, 2017 COGCC Environmental Staff (Alex Fischer), conducted an inspection of Grynberg Petroleum Company, (Grynberg) Location ID 312854, Pit Facility ID 100600, Remediation (REM) 8333. Jerry Hoberg (Moffat County Planning) was present. Weather was partially cloudy and temperatures about 70 degrees Fahrenheit at time of Inspection. REM 8333 had been an ongoing remediation since about April 2014 and was closed in June of 2017. The following is a summary:</p> <ul style="list-style-type: none"> The Location is fenced, gated and secured. There appeared to have been a recent precipitation event, as debris flow (vegetation) was noted about 6-8 inches entangled in the fence coming on Location from the west and off of Location to the east. A low lying "pond" had standing water. Sediment had moved across and off of Location. Erosion features were noted across Location. <p>On August 7, 2017, Alex Fischer contacted Randy Edlin (Grynberg) to let him know about the sediment leaving Location. Mr. Edlin directed Mr. Fischer to the Receivership (Mary Griggs).</p> <p>On August 8, 2017, Alex Fischer contacted Mary Griggs to let her know about the sediment leaving Location and referred her to Denise Arthur and Lou Colby (CGOCC Reclamation).</p> <p>NOTE: CONTACT REGARDING THE STORMWATER ISSUES Colby, Lou - Area (142) Reclamation Inspector lou.colby@state.co.us (970) 876-1969 (970) 989-4402 (cell)</p> <p>Arthur, Denise - Reclamation Supervisor denise.arthur@state.co.us (303) 894-2100 x5195 (720) 630-6533 (cell)</p>	fischera	08/07/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401367436	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218872

677900290	INSP Summary 20170803 Grynber Chivington Inspection Location ID 321854 Photo log.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218860
677900291	INSP Summary 20170803 Grynberg Location ID 312854 Pit Facility 100600 REM 8333.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218861