

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2017

Submitted Date:

08/07/2017

Document Number:

679100115**FIELD INSPECTION FORM**Loc ID 325845 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Naomi Azulai		naomi.azulai@bp.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:

Date of Inspection: 7-27-17

Type of Inspection: Flowline Hydrostatic Testing, Interim Reclamation, Containment, Stormwater

Location Name: Evelyn Payne Gas Unit F 1 Pad; Evelyn Payne F 1 and lateral

Location ID #: 325845

Form 2A# 401239603

API #: 05-067-07069

Construction stormwater BMPs for well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with rock check dams for sediment control) are in-place and these stormwater controls indicate no offsite migration of fluids or sediment; existing stormwater controls indicate no offsite migration of fluids or sediment to nearby ditch west of the well pad; cut and fill slopes have been partially to mostly re-vegetated; observed hydrostatic static testing of onsite water and gas flowlines from the wellhead to the separator and take away pipelines; all flowlines and pipelines were tested a minimum of 2 hours at pressures greater than estimated operating pressures (>950 psi); all flowlines and pipelines passed.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401367400	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218825