

Inspection Photos
Location Name: Josey 12-8 (1)
API: 05-123-10206



Photo from prior inspection for comparison



Photo 1: Signage reflects current operator



Inspection Photos
Location Name: Josey 12-8 (1)
API: 05-123-10206



Photo from prior inspection for comparison



Photo 2: Soil has been removed or remediated

Inspection Photos
Location Name: Josey 12-8 (1)
API: 05-123-10206



Photo from prior inspection for comparison



Photo 3: Tank has contents and capacity

Inspection Photos
Location Name: Josey 12-8 (1)
API: 05-123-10206



Photo from prior inspection for comparison



Photo 4: Signage is for current operator.