

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2017

Submitted Date:

08/08/2017

Document Number:

666803474

FIELD INSPECTION FORM

Loc ID 334911 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Contact, General		cogcc.inspections@encana.com	
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267971	WELL	PR	05/28/2004	GW	045-09227	HMU 3-9 (I3B)	PR
267979	WELL	PR	02/19/2004	GW	045-09234	HMU 3-16A (I3B)	PR
267980	WELL	PR	02/19/2004	GW	045-09235	HMU 2-13 (I3B)	PR
267983	WELL	PR	04/30/2004	GW	045-09237	HMU 2-12 (I3B)	PR
273281	WELL	PR	10/07/2005	GW	045-10228	HMU 3-7C (I3B)	PR
273282	WELL	PR	10/08/2005	GW	045-10230	GMU 34-16 (I3B)	PR
273284	WELL	PR	09/27/2005	GW	045-10234	HMU 3-7D (I3B)	PR
273285	WELL	PR	11/01/2005	GW	045-10231	HMU 3-8C (I3B)	PR
273286	WELL	AL	10/12/2006	LO	045-10233	GMU 35-13D (I3B)	AL
273287	WELL	PR	10/12/2005	GW	045-10232	HMU 2-12B (I3B)	PR

General Comment:

[Shared tank battery on location ID 334940](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Plunger Lift

9

Comment:

Corrective Action:

Date:

Type: Flow Line

#

Comment: [NTO, Comply with Rule 603.f . see photos](#)

Corrective Action: 24 hrs to lock out tag out. 30 days to remove riser

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

9

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	267971	Type:	WELL	API Number:	045-09227	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	267979	Type:	WELL	API Number:	045-09234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	267980	Type:	WELL	API Number:	045-09235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	267983	Type:	WELL	API Number:	045-09237	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	273281	Type:	WELL	API Number:	045-10228	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	273282	Type:	WELL	API Number:	045-10230	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	273284	Type:	WELL	API Number:	045-10234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	273285	Type:	WELL	API Number:	045-10231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 273286 Type: WELL API Number: 045-10233 Status: AL Insp. Status: AL

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 273287 Type: WELL API Number: 045-10232 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Culverts	Pass			
		Ditches	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401369629	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220635
666803475	NTO 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220630
666803476	NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220631