

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2017

Submitted Date:

08/08/2017

Document Number:

689300040**FIELD INSPECTION FORM**
 Loc ID 417959 Inspector Name: O'Donnell, Shaun On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 83555Name of Operator: SUNBURST INCAddress: 1401 E GIRARD STE 143City: ENGLEWOOD State: CO Zip: 80110**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		sun1045@aol.com	
Leonard, Mike		mike.leonard@state.co.us	
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417950	WELL	PR	10/29/2010	OW	123-31800	Moonshine 36-11-65	PR

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Sign at battery and entrance does not have current operator posted or emergency contact information		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/08/2017
Type	TANK LABELS/PLACARDS		
Comment:	Southwest crude oil tank does not have contents/capacity labeled. Water tank does not have NFPA diamond or capacity labeled. Propane tank is not labeled. NFPA labels on all oil tanks need to be replaced.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/08/2017

## Emergency Contact Number:

Comment:	Unreadable		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/08/2017

**Good Housekeeping:**

Type	OTHER		
Comment:	Open top container with freestanding fluid around stuffing box containment. No wildlife protection, stained soil where it is leaking		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.	Date:	09/08/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused rod next to northeast rig anchor		
Corrective Action:	Comply with Rule 603.f .	Date:	09/08/2017
Type	OTHER		
Comment:	Load line bucket on south side of tanks does not have an operable top. Standing fluid inside. Has stained soil around bucket. Need to have wildlife protection on load line bucket		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.	Date:	09/08/2017
Type	WEEDS		
Comment:	Actively growing weeds inside of tank berms and pump jack berms		
Corrective Action:	Comply with Rule 603.f .	Date:	08/18/2017
Type	UNUSED EQUIPMENT		
Comment:	1-1" Unused/unmarked riser north side of heater treater shed 4-2" Unused/unmarked risers north side of heater treater shed		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	09/08/2017
Type	TRASH		
Comment:	Trash inside of heater treater shed and pump jack shed. See attached photos		
Corrective Action:	Comply with Rule 603.f .	Date:	08/18/2017

Overall Good: ☐

<b>Spills:</b>			
----------------	--	--	--

Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>				corrective date	
Type: Ancillary equipment	# 1				
Comment: Propane tank					
Corrective Action:			Date:		
Type: Gas Meter Run	# 1				
Comment: Plumbed, no meter					
Corrective Action:			Date:		
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:			Date:		
Type: Pump Jack	# 1				
Comment:					
Corrective Action:			Date:		
Type: Flare	# 1				
Comment: Not in use					
Corrective Action:			Date:		
Type: Vertical Heater Treater	# 1				
Comment:					
Corrective Action:			Date:		
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:			Date:		
Type: Prime Mover	# 1				
Comment: Natural gas engine					
Corrective Action:			Date:		
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:			Date:		
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	<input type="text"/>				

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.870980,-104.602300
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Animal burrows in northeast of tank berms. See attached photos			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 09/08/2017

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 417950 Type: WELL API Number: 123-31800 Status: PR Insp. Status: PR**Producing Well**Comment: No recorded gas production

Corrective Action:

Date:

**BradenHead**Comment: Plumbed to surface

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401369596	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220619">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220619</a>
689300041	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220616">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220616</a>