

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/09/2017

Document Number:

674901862**FIELD INSPECTION FORM**

Loc ID 326087 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215841	WELL	PR	05/31/1990	GW	067-07446	KG TRUST 1	EI

**General Comment:**

On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP KG Trust #1. For the most recent field inspection report of this facility, please refer to document #680601166.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance. Lettering is peeling off of sign.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 08/21/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Sound walls on N, W, and E sides. Stock panel fencing on south side. Guard fencing present.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Stock panel fencing around separator and meter run.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Skid mounted.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215841	Type:	WELL	API Number:	067-07446	Status:	PR	Insp. Status:	EI

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP KG Trust #1. For the most recent field inspection report of this facility, please refer to document #680601166.	hughesj	08/09/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401370727	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221637">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221637</a>
674901863	Location sign is worn.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221632</a>
674901864	Weeds present on location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221633">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221633</a>
674901865	Risers marked as unused.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221634</a>