

Inspection Photos
Location Name: URSA
API: 05-045-12475



Photo 1. Overview of the project area from the southeastern corner facing center.



Photo 2. View of berm and cobble run-downs in the eastern portion of the project area from the southeastern corner facing northward.

Inspection Photos
Location Name: URSA
API: 05-045-12475

