

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2017

Submitted Date:

08/10/2017

Document Number:

680302216**FIELD INSPECTION FORM**

Loc ID 337102 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 75027Name of Operator: ROSEWOOD RESOURCES INCAddress: 2101 CEDAR SPRINGS RD STE 1500City: DALLAS State: TX Zip: 75201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone        | Email                 | Comment             |
|------------------|--------------|-----------------------|---------------------|
| Krehmeyer, James | 970-848-2228 | jkrehmeyer@rosewd.com | Cell # 970-630-3880 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 282324      | WELL | PR     | 12/30/2005  | GW         | 125-09805 | KORF* R 43-08 4N46W | PR          |

**General Comment:**

**Location**

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| <b>Lease Road:</b> |                                   |       |  |
| Type               | Access                            |       |  |
| comment:           | Located within irrigated cropland |       |  |
| Corrective Action  |                                   | Date: |  |

Overall Good: ☐

|                      |              |       |  |
|----------------------|--------------|-------|--|
| <b>Signs/Marker:</b> |              |       |  |
| Type                 | WELLHEAD     |       |  |
| Comment:             | Satisfactory |       |  |
| Corrective Action:   |              | Date: |  |

|                           |              |       |  |
|---------------------------|--------------|-------|--|
| Emergency Contact Number: |              |       |  |
| Comment:                  | Satisfactory |       |  |
| Corrective Action:        |              | Date: |  |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |            |       |  |
|--------------------|------------|-------|--|
| <b>Fencing/:</b>   |            |       |  |
| Type               | WELLHEAD   |       |  |
| Comment:           | Steel pipe |       |  |
| Corrective Action: |            | Date: |  |

|                          |            |       |                 |
|--------------------------|------------|-------|-----------------|
| <b>Equipment:</b>        |            |       | corrective date |
| Type: Gas Meter Run      | # 1        |       |                 |
| Comment:                 |            |       |                 |
| Corrective Action:       |            | Date: |                 |
| Type: Vertical Separator | # 1        |       |                 |
| Comment:                 |            |       |                 |
| Corrective Action:       |            | Date: |                 |
| Type: Other              | # 0        |       |                 |
| Comment:                 | Flowing GW |       |                 |
| Corrective Action:       |            | Date: |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Venting:</b>    |  |       |  |
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                 |  |  |
|-----------------|--|--|
| <b>Flaring:</b> |  |  |
| Type            |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 282324         | Type: WELL | API Number: 125-09805 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | Flowing GW |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|--|--|--|--|--|

**Reclamation - Storm Water - Pit****Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | In Process      | Other                   | In Process            |               |                          |         |

Comment: Located within irrigated cropland w/annual tillage

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment           | User     | Date       |
|-------------------|----------|------------|
| No problems found | schureky | 08/10/2017 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401372160    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222823</a> |