

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2017

Submitted Date:

08/11/2017

Document Number:

674901881

### FIELD INSPECTION FORM

Loc ID 325294 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96735  
 Name of Operator: WILLIFORD RESOURCES, L.L.C.  
 Address: 6506 S LEWIS AVE STE 102  
 City: TULSA State: OK Zip: 74136

**Findings:**

- 12 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	<a href="#">SW Insp Reports</a>
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	<a href="#">SW Insp Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214499	WELL	PR	07/01/1999	OW	067-06102	SPRING HOLLOW MAC 2	EI

**General Comment:**

On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Spring Hollow Mac #2. For the most recent field inspection report of this facility, please refer to document #667100610.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Free standing sign near tank battery.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type			
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil around well head.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>09/11/2017</u>
Crude Oil	Tank	<= 1 bbl	
Comment:	Stained soil benoath load out valves at tank battery.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>09/11/2017</u>
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date

Comment:	Electric motor.	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Well head is wet and stained with oil.	Date:	09/11/2017
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/11/2017
Type: Flow Line	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		37.128226,-108.092053
Comment:	Tank battery services Spring Hollow Mac #1, #2, and #3 wells.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		Date:	
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		Date:	
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 214499 Type: WELL API Number: 067-06102 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Spring Hollow Mac #2. For the most recent field inspection report of this facility, please refer to document #667100610. The well head is wet and stained with oil. The ground around the well head is stained with oil. The areas below the load out valves at the tank battery are oil stained.	hughesj	08/11/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401373386	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223876</a>
674901882	Tank battery with stained soil beneath load out valves.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223868">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223868</a>
674901883	Spring Hollow Mac #2 location photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223869">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223869</a>
674901884	Well head is wet, stained soil.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223870">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223870</a>