

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2017

Submitted Date:

08/11/2017

Document Number:

674901890

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325164 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96735  
 Name of Operator: WILLIFORD RESOURCES, L.L.C.  
 Address: 6506 S LEWIS AVE STE 102  
 City: TULSA State: OK Zip: 74136

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Callahan, Linda	918-749-8828	lcallahan3@swbell.net	<a href="#">SW Inspection Reports</a>
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	<a href="#">SW Insp Reports</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214178	WELL	SI	02/01/2017	OW	067-05498	LONG & SCHLUTER 1	EI

**General Comment:**

On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Long and Schluter #1. For the most recent field inspection report of this facility, please refer to document #685301167.

<b>Location</b>					
<b>Lease Road:</b>					
Type	Access				
comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:	Free standing sign next to pump jack.				
Corrective Action:					Date:
Type	BATTERY				
Comment:	Free standing sign located near AST.				
Corrective Action:					Date:
<b>Emergency Contact Number:</b>					
Comment:					Date: _____
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type					
Comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	PUMP JACK				
Comment:	Guard fencing on pump jack.				
Corrective Action:					Date:
<b>Equipment:</b>					
Type: Pump Jack	# 1				corrective date
Comment:	Electric motor.				
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		37.124992,-108.089949
Comment:					
Corrective Action:					Date:

<b>Paint</b>				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 214178 Type: WELL API Number: 067-05498 Status: SI Insp. Status: EI

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
<p>On August 3, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Long and Schluter #1. For the most recent field inspection report of this facility, please refer to document #685301167. A Professional Well Services work over rig and crew were on location during this inspection. Glenn Stevens, Williford Resources LLC representative, was also on site during this inspection. In addition to the work over rig, ancillary equipment included a skid mounted mud pit and three skid mounted compressors.</p>	hughesj	08/11/2017

**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401373828	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224592">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224592</a>
674901891	L and S #1 location photo with workover rig.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224588</a>
674901892	L and S #1 pump jack and well head.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224589</a>
674901893	L and S #1 300 bbl. AST.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224590">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4224590</a>