

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2017

Submitted Date:

08/11/2017

Document Number:

678300854**FIELD INSPECTION FORM**Loc ID 336504 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451656	TANK BATTERY	AC	08/08/2017		-	Camenisch 36N-22Hz battery	EI

General Comment:

inspection initiated by CDPHE report 2017-0405 regarding possible spill/release of E&P waste into surface water ponded to south of battery.

Battery is still under construction and not in operation at this time. Battery is located to south of wells it will serve and was located north of WCR 20.5 and north of ponded surface water. No spills or releases of E&P wastes from this battery were noted as battery not completed and not in service. Horizontal wells to north are drilled but not completed.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: not installed yet but battery not in use yet

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment: none observed at surface

☐ Multiple Spills and Releases?**Fencing/:**

Type TANK BATTERY

Comment: being installed at time of inspection

Corrective Action:

Date:

Equipment:

corrective date

Type: Horizontal Heated Separator # 6

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 2

Comment: one temporary

Corrective Action:

Date:

Type: #

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 8

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3		STEEL AST		,

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	5	500 BBLs	LVST		,	

Comment:	temporary	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent		Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 451656 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401373453	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4223948