

**Inspection Photos**  
**Location Name: Flatiron 10-36**  
**API: 05-123-12686**



**Wellhead sign looking west**



**Wellhead looking west. Well is TA, no MIT records**

**Inspection Photos**  
**Location Name: Flatiron 10-36**  
**API: 05-123-12686**



**Wellhead looking east at tank battery**



**Lease road looking east from wellhead to tank battery.  
Weeds need to be controlled**



**Inspection Photos**  
**Location Name: Flatiron 10-36**  
**API: 05-123-12686**



**West edge of location looking east at battery**



**Tank battery sign looking west at battery**

**Inspection Photos**  
**Location Name: Flatiron 10-36**  
**API: 05-123-12686**



**Unused/unmarked riser inside of tank berm on northwest corner**



**Flowline at separator is still in place. Dead weeds on south side of location pose a fire risk. Needs to be controlled.**