

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2017

Submitted Date:

08/18/2017

Document Number:

689300074**FIELD INSPECTION FORM**

Loc ID 323190 Inspector Name: O'Donnell, Shaun On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		mike.hickey@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	
Leonard, Mike		mike.leonard@state.co.us	
Precup, Jim		james.precup@state.co.us	
Mah, Steven		steven.mah@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244891	WELL	SI	04/01/2017	GW	123-12686	FLATIRON 10-36	TA

General Comment:

Wellhead is TA. Last recorded production was October 2014. Form 4 Sundry Doc #400565886 was approved 03/24/2014. A form 6 Doc #401038668 was approved 05/24/16 with an expiration date of 11/23/2016. No MIT test has been performed in accordance with rule 326b nor 326c.

Location			
Lease Road:			
Type	Access		
comment:	Access road from battery to wellhead has actively growing weeds. Needs to be controlled. See Housekeeping for CA.		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Actively growing weeds around the perimeter of location and access road from battery west to wellhead. Dead weeds along south side of location pose a potential fire risk. Needs to be controlled. See attached photos		
Corrective Action:	Comply with Rule 603.f .		Date: 08/28/2017
Type	UNUSED EQUIPMENT		
Comment:	Wellhead is TA. Last recorded production was October 2014. Form 4 Sundry Doc #400565886 was approved 03/24/2014. A form 6 Doc #401038668 was approved 05/24/16 with an expiration date of 11/23/2016. No MIT test has been performed in accordance with rule 326b nor 326c.		
Corrective Action:	Contact dnr_cogccengineering@state.co.us with resolution plan.		Date: 08/28/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	

Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	1 unmarked PVC riser inside of tank berm northwest of tank. See attached photos		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.442530,-104.721010	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV CONCRETE		,	
Comment:	48 BBL					
Corrective Action:						

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with crude oil tank			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 244891 Type: WELL API Number: 123-12686 Status: SI Insp. Status: TA**BradenHead**Comment: Bradenhead is plumbed to surfaceCorrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300075	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4231638