

Inspection Photos
Location Name: North Platte J-F-28HZ
API: 05-123-36024



Photo 1: Location, looking SE



Photo 2: Wellhead, looking NE



Inspection Photos
Location Name: North Platte J-F-28HZ
API: 05-123-36024



Photo 3: Stained soil at compressor



Photo 4: Stained soil at loadout valve

Inspection Photos
Location Name: North Platte J-F-28HZ
API: 05-123-36024



Photo 5: Riser at separator



Photo 6: Riser at engine

Inspection Photos
Location Name: North Platte J-F-28HZ
API: 05-123-36024



Photo 7: Riser at engine

