

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2017

Submitted Date:

08/14/2017

Document Number:

674901898**FIELD INSPECTION FORM**

Loc ID 325074 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213931	WELL	PA	11/11/2011	GW	067-05202	SOUTHERN UTE 32-8 1-1	EI
257024	WELL	PR	11/07/2013	GW	067-08293	SOUTHERN UTE 32-8; 1-7	EI
451653	SPILL OR RELEASE	AC	08/08/2017		-	SPILL/RELEASE POINT	EI

General Comment:

On August 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Southern Ute 32-8 #1-7. For the most recent field inspection report for this facility, please refer to document #685301776. Spill/release point ID #451653 has been created in the COGIS database for a release discovered on 8/4/17.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near separator. Old sign remains on site.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PA marker for 067-05202.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
Produced Water	Flow Line		
Comment:	Spill ID #451653.		
Corrective Action:	Submit supplemental spill report per Rule 906.b.		Date: 08/14/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Steel pipe barricade around PA marker for 067-05202.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Orange safety fencing around perimeter of excavation.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Stock panel fencing and guard fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID:	<u>213931</u>	Type:	<u>WELL</u>	API Number:	<u>067-05202</u>	Status:	<u>PA</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

Facility ID:	<u>257024</u>	Type:	<u>WELL</u>	API Number:	<u>067-08293</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

Facility ID:	<u>451653</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
--------------	---------------	-------	-----------------	-------------	----------	---------	-----------	---------------	-----------

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: [Refer to spill/release point ID #451653 for more information regarding this release.](#)Corrective Action: [Submit supplemental spill report per Rule 906.b.](#)

Date: 08/14/2017

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Erosion along eastern edge of pad.Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 09/14/2017

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Southern Ute 32-8 #1-7. For the most recent field inspection report for this facility, please refer to document #685301776. Spill/release point ID #451653 has been created in the COGIS database for a release discovered on 8/4/17. Construction crews were on site fabricating a new section of flow line. A trench has been opened up from the separator to the well head where the release occurred.	hughesj	08/14/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401374804	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225738
674901899	Erosion along eastern edge of pad.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225733
674901900	Erosion on eastern edge of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225734
674901901	Excavated area where release occurred.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225735
674901902	Welders fabricating new flow line.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225736
674901903	Excavated area near separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4225737