

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2017

Submitted Date:

08/14/2017

Document Number:

682402601**FIELD INSPECTION FORM**

Loc ID 319860 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201631	WELL	PR	09/09/1975	GW	001-07034	SMITH 20-4	RI

**General Comment:**

This is a stormwater inspection at the tank battery location. This is a short corrective action date due to erosion occurring off location. See the Stormwater section for more details. COGCC staff, Chris Binschus, contacted an Operator representative, Ed Ingvie, via phone on August 11, 2017, informing that a corrective action due date of Tuesday, August 15, 2017 would be issued.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

UNUSED EQUIPMENT

Comment:

Appears an unused tank is being stored at location and needs to be removed within 90 days of this inspection. Operator indicated during the phone call this tank might be used but was uncertain.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	201631	Type:	WELL	API Number:	001-07034	Status:	PR	Insp. Status:	RI

--

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: A point of discharge was observed along the western tank battery location. Gully erosion forming at location that is contributing to sediment discharge off location. Operator may need to install some form of a stabilized outlet (i.e., sediment trap) to control and manage stormwater to prevent sediment discharge off location. Please refer to the attached inspection photos for more details.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 08/15/2017

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401375440	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226411">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226411</a>
682402602	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226407">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226407</a>