

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2017

Submitted Date:

08/15/2017

Document Number:

681700730**FIELD INSPECTION FORM**

Loc ID 319841 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH CO ADDBA ENERGY SEARCH COAddress: PO BOX 1896City: EDWARDS State: CO Zip: 81632**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201542	WELL	PA	09/22/2016	OW	001-06945	GINTHER 1	EI

General Comment:

COGCC environmental inspection of former well location. Operator's authorization to conduct oil and gas operations in the state of Colorado was terminated under COGCC Order 1V-636.

Former well location does not meet final reclamation standards.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: No well sign, no emergency contact information.

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Wood, chain-link fence, fence posts, and concrete debris remain at former well pad.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Uncontrolled weeds at former well pad.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	~5' steel pipe riser marking former well location. Localized, oil-stained soil and gravel remain at former pump jack foundation.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201542 Type: WELL API Number: 001-06945 Status: PA Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401376494	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227273
681700785	Pipe riser, weeds, stained soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227261
681700786	unidentified monitoring well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227262
681700787	oily waste	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227263
681700788	wood debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227264
681700789	trash, weeds, gravel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227265
681700790	fencing and concrete debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227266
681700791	gravel and fence posts	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227267
681700792	concrete debris and weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227268
681700793	vertical boring at SW corner of former pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4227269