

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 1: Weeds at wellhead

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 2: Liner compromised by vegetation

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 3: Liner compromised

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 4: Weeds in tank battery



Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo 5: Tear in liner



Photo 6: Weed in liner

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo 7: Weeds along liner



Photo 8: Tears in liner, vegetation in liner