

Inspection Photos
Location Name: Dilka 6-12
API: 05-123-23783



Photo from prior inspection for comparison



Photo 1: Stained soil outside of separator

Inspection Photos
Location Name: Dilka 6-12
API: 05-123-23783



Photo from prior inspection for comparison




Photo 2: Stained soil in separator

Inspection Photos
Location Name: Dilka 6-12
API: 05-123-23783



Photo from prior inspection for comparison



Photo 3: Stormwater erosion mitigated

