

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2017

Submitted Date:

08/22/2017

Document Number:

685303667**FIELD INSPECTION FORM**Loc ID 325231 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214363	WELL	SI	01/01/1999	OG	067-05766	DUDLEY 1	SI

General Comment:

This is an orphan well inspection with emphasis on critical maintenance and abandonment. None of the previously identified corrective actions have been performed, corrective actions are still required.

With no current operator this orphan well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable pictures.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	3 not in use risers identified. Painted orange by inspector. Not in use - 3" steel line (W side of pump jack) with threaded nipple is open ended. Comes from W. Not in use - Steel riser and valve on SW corner of location. Not in use - Steel riser with elbow and plug in SW corner of location.		
Corrective Action:	5 days to mark and tag unused line(s) and 10 days to contact the Integrity group for discussion as per the CA matrix.		Date: 09/02/2016

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Steel mesh safety barrier.		
Corrective Action:			Date:

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment. Power comes in under ground to wellhead power panel. No power pole visible on perimeter of location.		
Corrective Action:			Date:
Type: Flow Line	# 5		

Comment:	In use - 3" steel line from wellhead casing. (B) point is unknown. In use - 3" steel line (W side of pump jack) comes in from S and ties into black poly line heading W. Not in use - 3" steel line (W side of pump jack) with threaded nipple is open ended. Comes from W. Not in use - Steel riser and valve on SW corner of location. Not in use - Steel riser with elbow and plug in SW corner of location.			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 1			
Comment:	Only 1 deadman located. Painted orange by inspector.			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 214363 Type: WELL API Number: 067-05766 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI - Production record indicates the well has been shut in since at least January 1999.
No MIT in electronic well file.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
If well is not returned to production tasks will likely include P&A, removal of production equipment, removal/abandonment of 5 flowlines, site clean up, impacted material removal, and removal of rig anchors. Completion of location and access road final reclamation work.	stjohnw	08/22/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303678	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234853