



photo 1: Facing west along the main road. There is signs of erosion along the road. Stormwater water is flowing down the road and is not being properly diverted. Road base material has eroded away.



photo 2: Facing northwest at the access road. Signs of erosion indicates stormwater is flowing down towards the main road. A culvert may be needed at this point.



photo 3: Facing west towards the location.



photo 4: There are noxious weeds (Bull thistle) growing around the location.