



photo 1: Facing west along the main road. There is signs of erosion along the road. Stormwater water is flowing down the road and is not being properly diverted.



photo 2: Facing down the road Stormwater is flowing down the road causing erosion.



photo 3: Facing further down the road to the southeast.



photo 4: There are signs of erosion occurring across the main road.



photo 5: Facing southwest toward the location.



photo 6: Well sign at the location.