

- Archuleta-Dix 1 05-067-07038



Photo 1: Wellhead sign previous inspection.

- Archuleta-Dix 1 05-067-07038



Photo 2: New wellhead sign.

- Archuleta-Dix 1 05-067-07038



Photo 3: Failed waddle and erosion channel in SW corner previous inspection.

- Archuleta-Dix 1 05-067-07038



Photo 4: Failed waddle and erosion channel in SW corner current inspection.

- Archuleta-Dix 1 05-067-07038



Photo 5: Erosion channel in SW corner previous inspection..

- Archuleta-Dix 1 05-067-07038



Photo 6: Erosion channel in SW corner current inspection.

- Archuleta-Dix 1 05-067-07038



Photo 7: Erosion channel in SW corner of location.

- Archuleta-Dix 1 05-067-07038



Photo 8: Same erosion channel as photo 7 in SW corner further down slope of location.