

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2017

Submitted Date:

08/24/2017

Document Number:

688000050**FIELD INSPECTION FORM**Loc ID 390294 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10380Name of Operator: BENCHMARK ENERGY LLCAddress: PO BOX 8747City: PRATT State: KS Zip: 67124**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**General Comment:**

Environmental inspection to document facility condition. See attached photographs.
Additional small quantity of oil spilled at the location of Spill ID #447951.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 1

Comment: Additional oil spilled at Spill ID #447951. Oil is pooled in the low area created during removal of soil from Spill 447951.

Corrective Action: Monitor location to see if this is just a temperature related one time event.

Date: 07/31/2017

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000051	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4236290