

Inspection Photos
Location Name: Wells Ranch USX BB 11-3
API: 05-123-25117



Photo 1: Wellhead, looking NE



Photo 2: Location, looking SW

Inspection Photos
Location Name: Wells Ranch USX BB 11-3
API: 05-123-25117



Photo 3: Decal damaged



Photo 4: Stained soil at valve