



photo 1: Facing northwest along the access road which has not been reclaimed.



photo 2: Facing northwest toward the location. The location has not been reclaimed and a pit remains at the location.



photo 3: The northeast toward the pit. The liner appears to be degraded and the fence around the pit is not maintained.



photo 4: Facing south toward the cut slope of the location.



photo 5: Facing southeast toward the location.



photo 6: Facing east along the north fill slope. There is predominately undesirable weeds (Russian thistle) throughout the location.



photo 7: Facing southwest toward the pit standing on top of the soil stockpile.



photo 8: Facing west toward the surrounding undisturbed pasture.