



photo 1: Facing southwest towards the storage yard of unused equipment, waste, and debris.
Lat/Long:39.94756,-104.42335



photo 2: Facing south toward the storage yard b of unused equipment, waste, and debris.



photo 3: There is oily waste around the barrels.



photo 4: Facing northeast toward the storage yard.



photo 5: Facing south where pipe riser was identified in the previous inspection. The pipe riser has been removed however this area has not yet been reclaimed.



photo 6: There is a t-post where the riser was removed. Lat/Long:39.94706,-104.42354