



photo 1: Facing west toward the beginning of the former access road.



photo 2: The pipe riser identified in the previous inspections was removed.

Lat/Long:39.93960,-104.71855



photo 3: Facing west beyond the location. Additional disturbance will need to be reclaimed.



photo 4: Facing east toward the location.