

Inspection Photos
Location Name: Dunn 1-13H
API # 123-34697



Photo 1. Sign



Photo 2. Stained soil at production tank leaking load line

Inspection Photos
Location Name: Dunn 1-13H
API # 123-34697



No netting containment



Wweeds at entrance & location