

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2017

Submitted Date:

08/22/2017

Document Number:

685303667

FIELD INSPECTION FORM

Loc ID 325231 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10254
Name of Operator: RED MESA HOLDINGS/O&G LLC
Address: 5619 DTC PARKWAY - STE 800
City: GREENWOOD State: CO Zip: 80111

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214363	WELL	SI	01/01/1999	OG	067-05766	DUDLEY 1	SI

General Comment:

This is an orphan well inspection with emphasis on critical maintenance and abandonment. None of the previously identified corrective actions have been performed, corrective actions are still required.

With no current operator this orphan well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable pictures.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	3 not in use risers identified. Painted orange by inspector. Not in use - 3" steel line (W side of pump jack) with threaded nipple is open ended. Comes from W. Not in use - Steel riser and valve on SW corner of location. Not in use - Steel riser with elbow and plug in SW corner of location.		
Corrective Action:	5 days to mark and tag unused line(s) and 10 days to contact the Integrity group for discussion as per the CA matrix.	Date:	09/02/2016

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Steel mesh safety barrier.		
Corrective Action:		Date:	

Equipment:

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Ancillary equipment	Wellhead.	# 1				
Pump Jack		# 1				
Prime Mover	Electric motor.	# 1				
Ancillary equipment	Electrical service equipment. Power comes in under ground to wellhead power panel. No power pole visible on perimeter of location.	# 1				
Flow Line		# 5				

Comment:	In use - 3" steel line from wellhead casing. (B) point is unknown. In use - 3" steel line (W side of pump jack) comes in from S and ties into black poly line heading W. Not in use - 3" steel line (W side of pump jack) with threaded nipple is open ended. Comes from W. Not in use - Steel riser and valve on SW corner of location. Not in use - Steel riser with elbow and plug in SW corner of location.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Only 1 deadman located. Painted orange by inspector.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 214363 Type: WELL API Number: 067-05766 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Production record indicates the well has been shut in since at least January 1999.
No MIT in electronic well file.

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
If well is not returned to production tasks will likely include P&A, removal of production equipment, removal/abandonment of 5 flowlines, site clean up, impacted material removal, and removal of rig anchors. Completion of location and access road final reclamation work.	stjohnw	08/22/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401383880	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234867
685303678	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234853