

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2017

Submitted Date:

08/22/2017

Document Number:

685303668**FIELD INSPECTION FORM**Loc ID 325247 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214395	WELL	SI	12/01/2006	OW	067-05811	DUDLEY 3	SI

General Comment:

This is an orphan well inspection with emphasis on critical maintenance and abandonment. None of the previously identified corrective actions have been performed, corrective actions are still required.

With no current operator this orphan well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable pictures.

Location has a domestic tap that appears to be in use. Valves are open at wellhead.

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel residential driveway.		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	2 risers not connected. Painted orange by inspector. Not in use - 1" riser at wellhead. Line is plugged. Not in use - 1" steel riser at domestic tap. Possible blow down line.		
Corrective Action:	5 days to mark and tag unused line(s) and 10 days to contact the Integrity group for discussion as per the CA matrix.	Date:	09/02/2016

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic tap - Valves open.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	In use - 3" steel line from wellhead tubing. Do not know where (B) point is. In use - 1" steel line from wellhead casing to domestic tap. Not in use - 1" riser at wellhead. Line is plugged. Not in use - 1" steel riser at domestic tap. Possible blow down line.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment. Power brought in to wellhead by buried line.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 214395 Type: WELL API Number: 067-05811 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Pump jack motor removed. Review of electronic well file record indicates well reported as TA since January 2014. Well was reported as SI from December 2006 until December 2013. Last reported production of oil and gas was 76/0 in November 2006. No MIT in electronic well file.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
If well is not returned to production tasks will likely include P&A, production equipment removal, removal/abandonment of 4 flowlines, identification and removal of electrical service, site clean up, impacted material removal, removal of rig anchors and junk & debris. Completion of final reclamation of location and access road.	stjohnw	08/22/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401383881	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234868
685303679	Electrical panel, Pump Jack, Domestic tap.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234854
685303680	Location overview.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234855