

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2017

Submitted Date:

08/22/2017

Document Number:

685303669**FIELD INSPECTION FORM**
 Loc ID 385333 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214054	WELL	SI	12/01/2014	OW	067-05346	DUDLEY 2	SI

General Comment:

This is an orphan well inspection with emphasis on critical maintenance and abandonment. None of the previously identified corrective actions have been performed, corrective actions are still required.

With no current operator this orphan well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel residential driveway.		
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Not in use - Steel riser on R side of wellhead. (B) point is unknown. Riser painted orange by inspector.		
Corrective Action:	5 days to mark and tag unused line(s) and 10 days to contact the Integrity group for discussion as per the CA matrix.		Date: 09/02/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment. No panel at wellhead but wiring is there.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	In use - 2" steel line from wellhead tubing. (B) point is unknown. Not in use - Steel riser on R side of wellhead. (B) point is unknown.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 214054 Type: WELL API Number: 067-05346 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA - Production equipment removed. Review of electronic well file indicates well was SI from January 1999 until December 2013. Well reported as TA since January 2014. No MIT in electronic well file.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
If well is not returned to production tasks will likely include P&A, removal of electrical service equipment, removal/abandonment of 2 flowlines, site clean up, and final reclamation work.	stjohnw	08/22/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401383882	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234869
685303681	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234856