

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 1. Methanol container knocked over with no secondary containment.



Photo 2. Land farm area with no containment. Berm around perimeter is unconsolidated and contains pieces of debris.

Inspection Photos
Location Name: Cody 1
API: 05-057-05135



Photo 3. Land farm area with no containment. Berm around perimeter is unconsolidated and contains pieces of debris.



Photo 4. Close up. Land farm area with no containment. Berm around perimeter is unconsolidated and contains pieces of debris.