

## Inspection Photos

Location Name: Colorado Energy Federal 14-3

API: 05-123-19617



Wellhead sign on motor shed looking north



Unused rods south side of pump jack motor shed looking east



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Stained soil under pump jack motor on north side, standing fluid appears to be used motor oil**



**Stained soil under pump jack motor on south side**



## Inspection Photos

Location Name: Colorado Energy Federal 14-3

API: 05-123-19617



Unused equipment along south wall in pump jack motor shed



Stained soil in pump jack motor shed from entrance door looking west



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Colorado Energy Federal 14-3

API: 05-123-19617



**Stained soil in skid of pump jack, north side. Standing fluid appears to be used motor oil.**



**Stained soil in skid of pump jack, north side.**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Stained soil in skid of pump jack on north side and middle.  
Standing fluid appears to be used motor oil leaking from pump  
jack motor**



**Stained soil in skid of pump jack, north side**

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Stained soil in skid of pump jack, center. Standing fluid appears to be used motor oil. 5 gallon bucket approx. half full with what appears to be used motor oil. No wildlife protection**



**Front of pump jack skid looking east. North side and center of skid have stained soil and standing fluid, 5 gallon open top container with no wildlife protection**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Unused equipment south side of pump jack**



**Stained soil around wellhead, looking east.**

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Pump jack from lease road looking northeast**



**36,000 gallon natural gas tank and 18,000 gallon propane tank on northwest corner of location, looking north**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Front of natural gas and propane tank looking west**



**Battery sign at entrance looking west**



## Inspection Photos

Location Name: Colorado Energy Federal 14-3

API: 05-123-19617



**2-2" unmarked/unused steel risers south side of east produced water tank**



**1-1" unused/unmarked steel riser south side of east middle produced water tank**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Leaking drain valve on south side of west crude oil tank**



**Stained soil on north side of west middle crude tank**

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Stained soil north side of east produced water tank**



**Crude oil tanks looking southwest. East tank has no NFPA label, west tank NFPA label not legible**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Produced water tanks looking south. East tank has correct labeling, west tank is labeled as crude oil and has produced water written under it. Uncertain of its contents. West tank needs NFPA label replaced.**



**Battery looking west from southeast edge of location**

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Location looking west from southeast edge of location**



**2" unused/marked poly line at heater treater shed entrance.  
No LOTO**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Stained soil in heater treater shed under oil leg from leaking valve**



**Leaking oil valve in heater treater**

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Stained soil in heater treater shed looking north from door**



**Circulating pump for tanks in heater treater shed**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Trash in heater treater shed, northeast corner**



**Trash in heater treater shed, southwest corner**

**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**Trash in heater treater shed, southeast corner**



**3" unused/marked steel riser, 2" unused/marked steel riser  
in heater treater. No LOTO**



**Inspection Photos**  
**Location Name: Colorado Energy Federal 14-3**  
**API: 05-123-19617**



**2-1" unused/unmarked steel risers north wall in heater treater shed**



**1-1" unused/unmarked steel riser north wall in heater treater shed**