

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2017

Submitted Date:

08/23/2017

Document Number:

685303685**FIELD INSPECTION FORM**Loc ID 325824 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Leonard, Mike		mike.leonard@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215433	WELL	PR	02/01/2016	GW	067-07038	ARCHULETA-DIX 1	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	New sign installed. Corrective action completed.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	New wellhead sign installed. Operator contact information posted on wellhead sign. Corrective action completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215433	Type:	WELL	API Number:	067-07038	Status:	PR	Insp. Status:	PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Pass			
Waddles	Fail					
Compaction	Fail	Compaction	Pass			

Comment: Erosion channel 4"-8" deep and 10"-18" wide off the SW corner of location is carrying stormwater and sediment off location. Corrective action not completed. Corrective action date remains the same.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 08/17/2017

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401385693	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4236292">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4236292</a>
685303693	Inspection pictures.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4236286">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4236286</a>