

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2017

Submitted Date:

08/28/2017

Document Number:

674901907**FIELD INSPECTION FORM**Loc ID 306936 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280384	WELL	SI	06/01/2017	GW	067-09076	MERRY FEDERAL 2	EI
451747	SPILL OR RELEASE	AC	08/22/2017		-	Merry Federal Gas Unit #2 002	EI

**General Comment:**

On August 25, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Merry Federal #2. For the most recent field inspection report for this facility, please refer to document #685303565. The purpose of this site visit was to inspect spill/release point ID #451747.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	PBV has label and placard on top of tank as well as on outside of containment ring.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Polished rod and well head are wet with oil.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date:	08/29/2017
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Stock panel fencing around well head and pump jack. Guard fencing on pump jack.			
Corrective Action:			Date:	
Type	SEPARATOR			
Comment:	Stock panel fencing around PBV, separator, meter run, and telemetry equipment.			
Corrective Action:			Date:	
<b>Equipment:</b>				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	

Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.232898,-107.511415	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	280384	Type:	WELL	API Number:	067-09076	Status:	SI	Insp. Status:	EI
Facility ID:	451747	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Slope Roughening	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Waddles	Pass					
Berms	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 25, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Merry Federal #2. For the most recent field inspection report for this facility, please refer to document #685303565. The purpose of this site visit was to inspect spill/release point ID #451747. Please refer to document #401374433 for more information regarding this release. The polished rod and the well head are wet with oil from a stuffing box leak. An absorbent wipe tied around the well head is saturated with oil. The location berm breach along the west side of the location has been repaired.	hughesj	08/28/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401389184	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4238918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4238918</a>
674901908	Polished rod and well head are wet with oil.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4238910">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4238910</a>
674901909	95 bbl. PW PBV with steel containment ring.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4238912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4238912</a>