



Photo 1: View of stormwater controls at the southern edge of the entrance to the well pad and access road. Need maintenance.



Photo 2: View of stormwater controls at the northern edge of the well pad entrance. Appear to be functioning.



Photo 3: View of cobble run down along the northwestern edge of the project area appears to be functioning at this time.



Photo 4: View of what appears to be surface owner debris in the southwestern portion of the project area. Corrective action to remove this has not been addressed.