

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2017

Submitted Date:

08/29/2017

Document Number:

678800395**FIELD INSPECTION FORM**

Loc ID 424350	Inspector Name: LEONARD, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10544</u> Name of Operator: <u>HIGHPOINT ENERGY LLC</u> Address: <u>361 71ST AVE</u> City: <u>GREELEY</u> State: <u>CO</u> Zip: <u>80634</u>				Findings: 4 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		mnotter@rocheconstructors.com	
Maxwell, Annette		Maxwell.Annette@epa.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424372	WELL	PR	07/12/2014	OW	123-33999	392 VENTURES 21-22D	TA
424375	WELL	PR	07/24/2014	OW	123-34000	392 VENTURES 22CD	TA
424380	WELL	PR	07/19/2014	OW	123-34002	392 VENTURES 22AD	TA
424382	WELL	PR	06/21/2014	OW	123-34004	392 VENTURES 32-22D	TA
424384	WELL	PR	09/08/2016	OW	123-34006	392 VENTURES 31-22D	TA
424386	WELL	PR	07/14/2014	OW	123-34008	392 VENTURES 41-22D	TA
424390	WELL	PR	06/21/2014	OW	123-34010	392 VENTURES 12-22D	TA
424391	WELL	PR	06/21/2014	OW	123-34011	392 VENTURES 42-22D	TA
424703	WELL	PR	06/24/2014	OW	123-34137	392 VENTURES 22JD	TA
424704	WELL	XX	02/27/2013	LO	123-34138	392 VENTURES 22RD	XX

General Comment:

Inspection performed in conjunction with EPA RCRA inspection. All wells appear o be TA'd for safety prep

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Oily fluids apparent on compressor skid and holes dug around skid. Buckets used to catch fluids have oily substance in them		
Corrective Action:	Remove fluid within 24 hours. Remediate soils around skids	Date:	08/29/2017
Type	OTHER		
Comment:	Wellhead equipment and pipe are stored in non-workman like fashion		
Corrective Action:	Comply with Rule 603.f .	Date:	09/25/2017
Type	WEEDS		
Comment:	Weeds are overgrowing north and eastside of location		
Corrective Action:	Comply with Rule 603.f .	Date:	09/09/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 424350 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective
Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>424372</u>	Type: <u>WELL</u>	API Number: <u>123-33999</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424375</u>	Type: <u>WELL</u>	API Number: <u>123-34000</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424380</u>	Type: <u>WELL</u>	API Number: <u>123-34002</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424382</u>	Type: <u>WELL</u>	API Number: <u>123-34004</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424384</u>	Type: <u>WELL</u>	API Number: <u>123-34006</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424386</u>	Type: <u>WELL</u>	API Number: <u>123-34008</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424390</u>	Type: <u>WELL</u>	API Number: <u>123-34010</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424391</u>	Type: <u>WELL</u>	API Number: <u>123-34011</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424703</u>	Type: <u>WELL</u>	API Number: <u>123-34137</u>	Status: <u>PR</u>	Insp. Status: <u>TA</u>
Facility ID: <u>424704</u>	Type: <u>WELL</u>	API Number: <u>123-34138</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401390630	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4240141
678800396	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4240139