



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner facing northward. What appears to be surface owner junk and debris is scattered throughout the interim reclamation area.



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of the northern portion of the project area from the northeastern corner facing westward. Exposed cut-slope is not stabilized.