

Photo#1:  
View to North over Location



August 23, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Farleigh Oil DA Silver Spur API#057-06459

Photo#2:

Close up of Land Farm area that has not revegetated.



August 23, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Farleigh Oil DA Silver Spur API#057-06459



Photo#3:

Close up of ground conditions & Vegetation in unsuccessfully revegetated areas.



August 23, 2017

Photo#4:

Canada Thistle is established in revegetated areas

