

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #1 – Well sign, pump jack, and shed.



Photo #2 – Oil-stained soil beneath prime mover.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #3 – Crude oil ASTs lacking earthen berm.



Photo #4 – Soil stockpile east of crude oil ASTs.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #5 – Localized, stained soil beneath east crude oil AST, as indicated in previous FIR.



Photo #6- Soil stockpile (possible former berm) at SW corner of tank battery. Note: junk/debris in background.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #7 – Former AST stairway and VHT shed debris located SW of crude oil AST.



Photo #8 – VHT.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #9 – Junk fence posts and barbed wire at NW corner of pit complex.



Photo #10 – Tinhorn skim pit with fluid remaining. Note: flowline risers in and outside of pit and damaged mesh (toward top of photo).

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #11 – Abandoned 2" flowline riser and 4" riser for valve control located NW of tinhorn.



Photo #12 – View of produced water pit, Facility ID #110650, from tinhorn (looking SE).

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #13 – View of produced water pit from tinhorn (looking SW). Note: localized, oil-stained waste underlying inlet from tinhorn.



Photo #14 – Oil-stained soil at NW corner of pit.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #15 – Oil-stained soil at NE corner of produced water pit.



Photo #16 – Oil-stained soil at SW corner of produced water pit.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #17 – Localized, oil-stained soil along south side of pit.



Photo #18 – Localized, oil-stained soil at SE corner of pit.

Inspection Photos
Location Name: Merino 1
API: 05-075-09094
Inspection Date: August 30, 2017



Photo #19 – Localized, oil-stained soil at NE corner of pit.



Photo #20 – Unused truck loadout containment device east of pit complex.