

Construction and Stormwater Inspection

September 6, 2017

Operator: SRC ENERGY INC- #10311

Location ID: 451277

Weld County, CO

NESE Section 11 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Falken /9-11 Pad
Location ID: 451277



Photo 1. Photo taken from the entrance of the well pad location, facing North. Tracking pad device installed at location.



Photo 2. Photo taken from the southeast well pad location, facing West. Ditch and berm BMP installed around the perimeter of the well pad location.

Inspection Photos
Location Name: Falken /9-11 Pad
Location ID: 451277



Photo 3. Photo taken from the southeast well pad location, facing North. Ditch and berm BMP installed around the perimeter of the well pad location.



Photo 4. Photo taken from the northeast well pad location, facing North. Sediment trap embankment berms have not been compacted and still needs a stabilized outlet structure.

Inspection Photos
Location Name: Falken /9-11 Pad
Location ID: 451277



Photo 5. Photo taken from the northeast well pad location, facing West. Sediment trap installed with a stabilized outlet structure.



Photo 6. Photo taken from the northwest well pad location, facing South. Ditch and berm BMP installed around the perimeter of the well pad location. Also, photo illustrates topsoil stockpile stored along the west perimeter of the location.

Inspection Photos
Location Name: Falken /9-11 Pad
Location ID: 451277



Photo 7. Photo taken from the southeast production facility, facing North. Only an unconsolidated berm along the eastern perimeter of the location.



Photo 8. Photo taken from the southern production facility, facing Northwest. No observed BMP. Topsoil material still needs to be stored.

Inspection Photos
Location Name: Falken /9-11 Pad
Location ID: 451277



Photo 9. Photo taken from the western production facility, facing Northwest. No observed BMP. Topsoil material still needs to be stored.



Photo 10. Photo taken from the entrance of the production facility, facing East. Tracking pad device installed at location. Unconsolidated berm observed along portions of the northern production facility.