

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2017

Submitted Date:

09/06/2017

Document Number:

685303725**FIELD INSPECTION FORM**Loc ID 333643 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16695Name of Operator: CHEVRON MIDCONTINENT LPAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**27 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Pohl, April	505-333-1941	april.pohl@chevron.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216182	WELL	PR	01/30/2008	GW	067-07788	CLARK 7-1	PR
277257	WELL	PR	02/01/2011	GW	067-09036	CLARK 7 2	SI

General Comment:[See link at end of report for path to downloadable pictures.](#)[Inspection report contains corrective action and comment.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal framed sign located at wellhead.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tank.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Busted concrete chunks in NW corner of location.		
Corrective Action:	Remove concrete debris to comply with Rule 603.f.		Date: 10/07/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused 1" steel riser at Clark 7-2 wellhead. Flowline risers not LO/TO or marked are considered unused equipment. Riser not locked out, tagged out, or painted.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 10/07/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	6' Chainlink fencing topped with 3 strands of barbwire.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Safety rails.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Pig Station - Concrete barriers.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	In use - 4" steel line from Clark 7-1 wellhead tubing to separator inlet. All points co-located. In use - 4" steel line from Clark 7-1 wellhead casing to separator inlet. All points co-located. In use - 6" steel line from separator outlet to gas meter inlet. All points co-located. In use - 1" steel line from separator outlet to produced water tank. All points co-located. In use - 1" steel line from separator sales line into ground. (B) point unknown. Not found on submitted inventory.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank and pump on spill prevention.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	In use - 2" steel line from Clark 7-2 wellhead tubing to separator inlet. All points co-located. In use - 4" steel line from Clark 7-2 wellhead casing to separator inlet. All points co-located. In use - 6" steel line from Clark 7-2 separator outlet to gas meter inlet. All points co-located. Not in use - 1" steel riser at Clark 7-2 wellhead from separator outlet. All points co-located. In use - 1" Steel line from separator outlet to produced water tank. All points co-located. In use - 1" steel gas line from separator sales outlet into ground. (B) point unknown. Not found on submitted inventory.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:	Partially buried steel tank with earthen berms.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Dried grass noted inside containment berms.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 216182 Type: WELL API Number: 067-07788 Status: PR Insp. Status: PR**Producing Well**Comment: PR - Review of electronic well file indicates last reported production as June 2017.

Corrective Action:

Date:

Facility ID: 277257 Type: WELL API Number: 067-09036 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Horse head and pump jack removed at time of inspection. Review of electronic well file indicates last reported production was June 2017.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: [Rural residential properties.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment Thistle growing in perimeter outside fenced area. Similiar issue identified in previous inspection.

Corrective Action Comply with Rule 1003.f.

Date **10/07/2017**

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			Chemical tank on spill prevention.
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tank.
Sediment Traps	Pass					
Gravel	Pass					

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303734	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4245453