

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2017

Submitted Date:

09/07/2017

Document Number:

685100252

**FIELD INSPECTION FORM**

Loc ID 313094 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10428  
Name of Operator: DIVERSIFIED ENERGY LLC  
Address: 19501 E MAIN STREET #200  
City: PARKER State: CO Zip: 80138

**Findings:**

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Haack, Jason		jhaack@oagproduction.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223587	WELL	PR	07/01/2017	OW	081-06954	BINGMAN 1-14	SI
448928	LAND APPLICATION SITE	AC	01/12/2017		-	BINGMAN LAND TREATMENT	EI

**General Comment:**

COGCC staff, Kris Neidel Inspected the Bingman #1-14 on 8/9/2017 the weather was cloudy and 80 degs. Upon arrival, it was observed that the road had recently been bladed, it appeared that soil had been added to road. The berms around the production tanks had been increased in size, piece of plastic can be seen incorporated into the berm. There were pieces of plastic, what appeared to be liner material around the location; incorporated in the pad, on the pad, incorporated in the berm, incorporated in the access road, Inspector stopped counting plastic pieces at 26. . The stockpiled material that was a part of Remediation Project number 10272 is no longer piled on location. The well was SI at the time of inspection. Operator should continue to communicate with COGCC staff for plan forward to compliance. and plans set out in Remediation Project.

Location			
<b>Lease Road:</b>			
Type			
comment:	Access road appears to have been graded recently. Plastic liner pieces were observed on entire roadway from gate to location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/21/2017
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	303-995-0826		Date:
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Plastic liner pieces in tank berm and around location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/21/2017
Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/21/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Flow Line	#		corrective date
Comment:	2 - 2" steel risers observed at 40.38894, -108.13606 and 1 - 2" steel riser observed in tank berm not locked out tagged out.		

Corrective Action:	"Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."	Date:	08/21/2017
--------------------	--	-------	------------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	08/04/2017

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:	Operator should ensure that berms are adequately impermeable. Any trash incorporated in the berms should be removed.			Date:	

**Venting:**

Yes/No					
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 223587 Type: WELL API Number: 081-06954 Status: PR Insp. Status: SI

**Producing Well**

Comment:

Corrective Action:

Date:

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current MIT on record or delinquent as required by Rule 326. Well has been shut-in since September 2015. MIT will be needed this September 2017.

Corrective Action: No current MIT on record or delinquent as required by Rule 326. Well has been shut-in since September 2015. MIT will be needed this September 2017.

Date: 09/30/2017

Facility ID: 448928 Type: LAND API Number: - Status: AC Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100253	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4245661">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4245661</a>