

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2017

Submitted Date:

09/07/2017

Document Number:

685503743**FIELD INSPECTION FORM**
 Loc ID 451659 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 5950 CEDAR SPRINGS ROADCity: DALLAS State: TX Zip: 75235**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
BEECHERL, ARTHUR	214-728-1840	abeecherl@beecherl.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451674	WELL	DG	09/05/2017		123-45163	WARNER 01N-64W-17-2H	DG

General Comment:

Location**Lease Road:**

Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	INSIDE RIG PUSHERS OFFICE	Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 451674 Type: WELL API Number: 123-45163 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: EXTREME 20 Pusher/Rig Manager: MIKE MAGNESS
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: YES
 Multi-Well: YES Disposal Location: WASTE MANAGMENT

Comment: JUST CEMENTING SURFACE, BOP'S ARE NOT ON WELL, DRILLING MUD AND GEL IN CONTAINMENTS, NO TRASH AROUND LOCATION, BMP'S ARE GOOD, WASTE OIL AND GOOD OIL ON CONTAINMENT
 @ BOP'S WILL BE PUT ON TOMORROW, JUST DRILLING SURFACE CSG

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
RIG INSPECTION	montoyaj	09/07/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685503744	BMP'S AROUND LOCATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4246265