

Inspection Photos
Location Name: Parr-State #28-1
API: 05-005-06431
Inspection Date: September 7, 2017



Photo #1 – Well sign.



Photo #2 – Localized, stained soil beneath day tank and prime mover.

Inspection Photos

Location Name: Parr-State #28-1

API: 05-005-06431

Inspection Date: September 7, 2017



Photo #3 – Localized, oil-stained soil beneath prime mover.



Photo #4 – Localized, oil-stained soil at wellhead. Note oily rag tied above stuffing box.



Inspection Photos

Location Name: Parr-State #28-1

API: 05-005-06431

Inspection Date: September 7, 2017



Photo #5 – Battery sign.



Photo #6 – Tank battery (view from SW corner).



Inspection Photos

Location Name: Parr-State #28-1

API: 05-005-06431

Inspection Date: September 7, 2017



Photo #7 – View of tank battery from NE corner. Note that berm is shallow due to erosion.



Photo #8 – Localized, oil-stained soil beneath valve on north side of produced water AST. Note uncapped pipe in center of photo.



Inspection Photos

Location Name: Parr-State #28-1

API: 05-005-06431

Inspection Date: September 7, 2017



Photo #9 – Oily rag near truck loadout.



Photo #10 – Heated horizontal separator with barbed wire fence and bird protection.



Inspection Photos

Location Name: Parr-State #28-1

API: 05-005-06431

Inspection Date: September 7, 2017



Photo #11 – Localized, oil-stained soil and equipment on north side of separator.



Photo #12 – Flowlines referenced in 6/22/2017 FIR have been removed in accordance with corrective actions.

