

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2017

Submitted Date:

09/07/2017

Document Number:

681700865**FIELD INSPECTION FORM**

Loc ID 413721 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412570	WELL	PR	05/31/2012	OW	005-07144	Par State 28-14 #2	EI

General Comment:

[COGCC Environmental follow-up to inspection report #681700581. See inspection report #681700864 for inspection of shared equipment at tank battery.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Localized, oil-stained soil beneath prime mover. See photos.			
Corrective Action:	Remove and properly dispose of oily waste, per Rule 907.e.			Date: 09/15/2017
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Localized, oil-stained soil at wellhead. See photos.			
Corrective Action:	Remove and properly dispose of oily waste, per Rule 907.e.			Date: 09/15/2017

In Containment: No

Comment:

☒ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Barbed wire.		
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:	Localized, oil-stained soil at wellhead. See photos. Field inspection reports dating back to at least 11/15/2016 (docs #681700581 & #673714410) document recurring issue of localized, oil-stained soil beneath prime mover and wellhead/stuffing box.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 10/07/2017
Type: Prime Mover	# 1		
Comment:	Localized, oil-stained soil beneath prime mover. See photos. Field inspection reports dating back to at least 11/15/2016 (docs #681700581 & #673714410) document recurring issue of localized, oil-stained soil beneath prime mover and wellhead/stuffing box.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 10/07/2017
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected FacilitiesFacility ID: 412570 Type: WELL API Number: 005-07144 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700866	Stained soil beneath prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4246333
681700867	Well sign and shed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4246336
681700868	Stained soil at wellhead (1).	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4246338
681700869	Stained soil at wellhead (2).	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4246340