

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2017

Submitted Date:

09/08/2017

Document Number:

685303713**FIELD INSPECTION FORM**
 Loc ID 322095 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**31 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name       | Phone        | Email                       | Comment |
|--------------------|--------------|-----------------------------|---------|
| Labowskie, Steve   |              | steve.labowskie@state.co.us | COGCC   |
| Rabinowitz, Daniel | 970-385-1363 | drabinow@blm.gov            | Durango |
| Telecky, Barbara   |              | btelecky@blm.gov            | Durango |
| Leonard, Mike      |              | mike.leonard@state.co.us    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 208955      | WELL | PR     | 05/31/1982  | GW         | 033-06060 | FEDERAL 1-19  | SI          |

**General Comment:**[See link at end of report for path to downloadable pictures.](#)[Inspection completed to inventory flowlines/risers and check compliance to May 2017 Flowline NTO.](#)[Inspection report contains corrective action and comment.](#)

| Location   |  |          |                  |
|--|--|----------|------------------|
| <b>Lease Road:</b>                                     |  |          |                  |
| Type   | Access   |          |                  |
| comment:   | Dirt and gravel access road.   |          |                  |
| Corrective Action                                      | L  |          | Date:            |
| Overall Good: <input type="checkbox"/>                 |  |          |                  |
| <b>Signs/Marker:</b>                                   |  |          |                  |
| Type   | WELLHEAD   |          |                  |
| Comment:   | Metal sign at tank battery.  |          |                  |
| Corrective Action:                                     |  |          | Date:            |
| Type   | TANK LABELS/PLACARDS   |          |                  |
| Comment:   | Labels directly on tanks.  |          |                  |
| Corrective Action:                                     |  |          | Date:            |
| Emergency Contact Number:                              |  |          |                  |
| Comment:   | Operator contact information posted on wellhead sign. 505-326-3753 goes to voicemail for the offices of D J Simmons.                                       |          |                  |
| Corrective Action:                                     |  |          | Date:            |
| <b>Good Housekeeping:</b>                              |  |          |                  |
| Type   | UNUSED EQUIPMENT   |          |                  |
| Comment:   | Identified (18) unused risers on location. Flowline risers not LO/TO or marked are considered unused equipment.<br><br>Risers painted orange by inspector. |          |                  |
| Corrective Action:                                     | Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.  |          | Date: 10/08/2017 |
| Type   | OTHER  |          |                  |
| Comment:   | Impacted soil noted on backside of oil tank load out. Less than 5 gallon bucket clean up.  |          |                  |
| Corrective Action:                                     |  |          | Date:            |
| Type   | OTHER  |          |                  |
| Comment:   | Impacted soil noted at wellhead. Less than a 5 gallon bucket clean up.   |          |                  |
| Corrective Action:                                     |  |          | Date:            |
| Overall Good: <input type="checkbox"/>                 |  |          |                  |
| <b>Spills:</b>   |  |          |                  |
| Type   | Area   | Volume   |                  |
| Other  | Truck Loadout  | <= 1 bbl |                  |
| Comment:   | Spill prevention on water tank loadout is full and has overflowed.   |          |                  |
| Corrective Action:                                     | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.  |          | Date: 10/08/2017 |
| In Containment: No                                     |  |          |                  |
| Comment:   |  |          |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |  |          |                  |
| <b>Fencing/:</b>                                       |  |          |                  |
| Type   | TANK BATTERY   |          |                  |

|                           |   |  |                 |  |
|---------------------------|---|--|-----------------|--|
| Comment:                  | Steel T-Post and hog wire.  |  | Date:           |  |
| Corrective Action:        |   |  | Date:           |  |
| Type                      | PUMP JACK   |  |                 |  |
| Comment:                  | Safety rails.   |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type                      | SEPARATOR   |  |                 |  |
| Comment:                  | Steel t-post and hog wire.  |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| <b>Equipment:</b>         |   |  | corrective date |  |
| Type: Gas Meter Run       | # 1   |  |                 |  |
| Comment:                  |   |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type: Flow Line           | # 5   |  |                 |  |
| Comment:                  | Tank battery.<br>Outside fencing.<br>Not in use - 3" steel riser with valve and bull plug. (B) point unknown.<br>Not in use - 3" steel riser with valve and plug and check valve and plug. (B) point unknown.<br>Not in use - 3" steel riser with plug. (B) point unknown.<br>Inside fencing.<br>Not in use - 3" steel riser with plug. (B) point unknown.<br>Not in use - 4" steel riser with plug. (B) point unknown.   |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type: Bird Protectors     | # 1   |  |                 |  |
| Comment:                  |   |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type: Ancillary equipment | # 1   |  |                 |  |
| Comment:                  | Electrical service equipment. Electrical panel and (3) power poles bringing power to location.  |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type: Flow Line           | # 5   |  |                 |  |
| Comment:                  | At gas meter run house.<br>Not in use - (5) 3" steel risers beside and behind meter house. 1 is plugged and 4 are open ended. (B) point is unknown.   |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type: Prime Mover         | # 1   |  |                 |  |
| Comment:                  | Electric motor.   |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |
| Type: Flow Line           | # 10  |  |                 |  |
| Comment:                  | In use - 3" steel line from wellhead to separator inlet. All points co-located.<br>In use - 3" steel line from wellhead to separator inlet. All points co-located.<br>In use - 3" steel line from separator outlet to gas meter run inlet. All points co-located.<br>In use - 3" steel line from separator water dump to tank. All points co-located.<br>In use - 3" steel line from separator oil dump to tank. All points co-located.<br>In use - (3) 3" steel lines from separator. (B) point unknown. Could be tied to lines outside N side fencing.<br>In use - 1" steel line off wellhead casing. (B) point unknown.<br>Not in use - 1" steel riser with valve and plug at wellhead. (B) point unknown. |  |                 |  |
| Corrective Action:        |   |  | Date:           |  |

|                                   |  |       |
|-----------------------------------|--|-------|
| Type: Flow Line                   | # 7  |       |
| Comment:                          | N side of separator outside fenced area.<br>Not in use - 3" steel riser. Open ended hammer union. (B) point unknown.<br>Not in use - 1" steel riser. Open ended. (B) point unknown.<br>Not in use - 1" steel riser with valve. Not plugged. (B) point unknown.<br>Not in use - 3" steel riser with open ended swedge. (B) point unknown.<br>Not in use - 1" steel riser. Open ended. (B) point unknown.<br>Not in use - 1/2" steel riser with valve. Open ended. (B) point unknown.<br>Not in use - 1/8" stainless steel riser. Open ended. (B) point unknown. |       |
| Corrective Action:                |  | Date: |
| Type: Deadman # & Marked          | # 4  |       |
| Comment:                          |  |       |
| Corrective Action:                |  | Date: |
| Type: Pump Jack                   | # 1  |       |
| Comment:                          |  |       |
| Corrective Action:                |  | Date: |
| Type: Horizontal Heated Separator | # 1  |       |
| Comment:                          |  |       |
| Corrective Action:                |  | Date: |
| Type: Ancillary equipment         | # 1  |       |
| Comment:                          | Wellhead.  |       |
| Corrective Action:                |  | Date: |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type      | Tank ID | SE GPS |
|--------------------|--|----------|-----------|---------|--------|
| PRODUCED WATER     | 1  | OTHER    | STEEL AST |         |        |
| Comment:           | Above ground 210 BBL steel tank with earthen berms.<br>THERE IS 1'10" FLUID IN THE TANK AT TIME OF INSPECTION. |          |           |         |        |
| Corrective Action: |  |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 210 BBLs |
| Other (Type)     |          |

**Berms**

| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |        |
|--------------------|---|---------------------|---------------------|-------------|--------|
| Earth              | Adequate  | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           | Berms are weathering.   |                     |                     |             |        |
| Corrective Action: |   |                     |                     | Date:       |        |
| Contents           | #   | Capacity            | Type                | Tank ID     | SE GPS |
| CRUDE OIL          | 3   | 400 BBLs            | STEEL AST           |             |        |
| Comment:           | Above ground 400 BBL steel tank with earthen berms.<br>THERE ARE FLUIDS IN THE TANKS AT TIME OF INSPECTION.<br>Tank 1 - 3' 7"<br>Tank 2 - 0' 8"<br>Tank 3 - 2' 1" |                     |                     |             |        |

|                                |          |                     |                     |             |       |  |
|--------------------------------|----------|---------------------|---------------------|-------------|-------|--|
| Corrective Action:             |          |                     |                     |             | Date: |  |
| <b>Paint</b>                   |          |                     |                     |             |       |  |
| Condition                      | Adequate |                     |                     |             |       |  |
| Other (Content)                |          |                     |                     |             |       |  |
| Other (Capacity)               |          |                     |                     |             |       |  |
| Other (Type)                   |          |                     |                     |             |       |  |
| <b>Berms</b>                   |          |                     |                     |             |       |  |
| Type                           | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |  |
| Earth                          | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |  |
| Comment: Berms are weathering. |          |                     |                     |             |       |  |
| Corrective Action:             |          |                     |                     |             | Date: |  |
| <b>Venting:</b>                |          |                     |                     |             |       |  |
| Yes/No                         | NO       |                     |                     |             |       |  |
| Comment:                       |          |                     |                     |             |       |  |
| Corrective Action:             |          |                     |                     |             | Date: |  |
| <b>Flaring:</b>                |          |                     |                     |             |       |  |
| Type                           |          |                     |                     |             |       |  |
| Comment:                       |          |                     |                     |             |       |  |
| Corrective Action:             |          |                     |                     |             | Date: |  |

**Inspected Facilities**Facility ID: 208955 Type: WELL API Number: 033-06060 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI - Review of electronic well file indicates last reported oil/gas production was December 2015 with 503/1226 production reported. Well has been reported as SI since January 2016 with last production report submitted May 2017.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Location on edge of canyon to the N and agricultural fields to the S.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐



**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                        |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--------------------------------|
|                  |                 | Gravel                  | Pass                  |  |                          |                                |
|                  |                 | Culverts                | Pass                  |  |                          |                                |
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Pass                     | Berms around production tanks. |

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| There are currently fluids in the tanks. May 2017 Flowline NTO not completed. Inspector identified and painted orange (18) unused risers at the time of inspection. | stjohnw | 08/30/2017 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 685303722    | Inspection pictures. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247087">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247087</a> |